





MANDATORY SERVICE BULLETIN
No. UL 02/2021, Rev. 00

Page: 1 / 1

PROPELLER GOVERNOR REPAIR

This Service Bulletin is issued in line with the procedures subject to LAA ČR no. 34/92 authorisation

Type certificate holder: Woodcomp Propellers s.r.o.	Type / Model: Propeller governors P-110-030/A, P-110-060/A Jihostroj hydraulic propeller governors
Type certificate number	The governors are useful for various WOODCOMP hydro-mechanical propellers
Related documents	Jihostroj a.s.: Quality Notification issued on August 11, 2021
Replaces	N/A
Manufacturer	Jihostroj a.s.
Applies to	P-110-030/A, S/N: 211105, 211106 P-110-060/A, S/N: 211054, 211055, 211092, 211156, 211158, 211159, 211160
Reason	It has been found that the above listed governors contain a part that does not meet the prescribed production quality. Failure of this part may affect the proper work of the governor resulting in loss of its functionality after a relatively short time.
Effective date	18 AUG 2021
Work procedure	N/A
Action	1. Dismount the propeller governor from the engine. 2. Send the governor to the producer for repair: Jihostroj a.s. Aerospace Division Budějovická 148 382 32 Velešín Czech Republic
Work to be performed by	By service organization authorized by the aircraft manufacturer
Schedule	Immediately
Cost covered by	Jihostroj a.s.
Material necessary	N/A
Remarks	N/A

Manager Accountable: Name: Aleš Křemen Sign: 	Quality Manager: Name: Vilém Pompe Sign: 	Rev. 00 Date: 18 AUG 2021
--	--	--