

| Title: ETFE Earth and Power Cable Colour Change | | | |
|---|----------------------------|------------------------------|--|
| AG-SIL-2023-01-EN | | Released: | |
| Applicability | | 1st October 2022 | |
| Aircraft type & model: | Affected Serial number(s): | 1 st October 2023 | |
| All models equipped with ETFE cables | From March 2023 | | |
| The maintenance manual to be referenced is this stated or subsequent issue. As per AutoGyro websit | | As per AutoGyro website | |
| This form is the response from AutoGyro GmbH either against a problem found in the product in service requiring a containment or rectification action, or as service information for aircraft modification incorporation. | | | |

For help, contact AutoGyro, email: airworthiness@auto-gyro.com.

Documentation (Service Information Letter Completion action)

The purpose of this document is to provide maintenance personnel with information over and above that currently available in the relevant AMM. Its compliance must be properly documented, if such procedure is required by the relevant authority

| Document approval signatures | | |
|--|-----------------------|--|
| Head of Engineering | Head of Airworthiness | |
| | | |
| The technical content of this document is approved under the authority of the UK CAA Design Organisation Approval Ref: DAI/9917/06 | | |

| Contact & Info: | AutoGyro GmbH |
|-----------------------------|------------------|
| airworthiness@auto-gyro.com | Dornierstr. 14 |
| www.auto-gyro.com | 31137 Hildesheim |
| | |



Reason and overview of the Service Information Letter

The aim of this SIL is to inform our Maintenance Partner and customer that AutoGyro changed the colour of the ETFE Power and Earth cables. They will no longer be white with a RD or BLK stamp. From now on the Power and Earth cables will be red and black coloured.

Manpower estimates

There are no manpower estimates associated with this SIL.

Compliance

There are no compliance requirements associated with this SIL.

Customer Support

Can be contacted if necessary.

Tooling required

No tools required.

Weight and Balance Effects

Nil

Manuals affected

POH & AMM AutoGyro is not affected

Previous Modifications that affect the SIL

None

Accomplishment instructions (Action required to implement this SIL):

None

Any life-limit changes must be recorded within the aircraft documentation, in line with the requirements of the country of operation.

Nil

Material information (Parts required relevant to this service information letter):

Nil

List of components (with purchasable part numbers)

Nil

Contact & Info: airworthiness@auto-gyro.com www.auto-gyro.com



Interchangeability

Not affected

Parts disposition

- a) Disposal requirements Nil
- b) Environmental hazards of parts containing hazardous materials Nil
- c) Scrap requirements (e.g. mutilate scrapped items beyond use) Nil

| Contact & Info: |
|-----------------------------|
| airworthiness@auto-gyro.com |
| www.auto-gyro.com |